



09 802 8240

Docket No.: TESSERA 3.0-236
(PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of:
Beroz et al.

Patent No.: 6,794,202 *B2*

Issued: September 21, 2004

For: ASSEMBLIES FOR TEMPORARILY
CONNECTING MICROELECTRONIC
ELEMENTS FOR TESTING AND METHODS
THEREFOR

Certificate
DEC 01 2004
of Correction

Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.323

Dear Sir:

Enclosed herewith is an original and one copy of a Certificate of Correction with respect to the above-identified U.S. Patent. You are hereby authorized to charge Deposit Account No. 12-1095 in the amount of \$100 to cover the required fee for filing a Certificate of Correction under § 1.323.

These errors were inadvertent, occurred in good faith and do not involve any changes which constitute new matter.

We look forward to early return of the copy of the Certificate of Correction duly certified.

Dated: November 22, 2004

Respectfully submitted,

By Michael J. Doherty

Michael J. Doherty
Registration No.: 40,592
LERNER, DAVID, LITTENBERG,
KRUMHOLZ & MENTLIK, LLP
600 South Avenue West
Westfield, New Jersey 07090
(908) 654-5000

Attorney for Applicant

11/29/2004 NROCHA1 00000023 121095 6794202

01 FC:1811 100.00 DA

LD-449\

8 DEC 2004

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,794,202 *B2*
DATED : September 21, 2004
INVENTOR(S) : Masud Beroz and David Light

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, line 25, after "integrated circuits" insert --,--.
Column 1, line 52, delete "are" and insert therefor --is--.
Column 4, line 53, after "combination" insert --of--.
Column 5, line 33, delete ",".
Column 5, line 55, delete "in" and insert therefor --is--.
Column 9, line 19, after "as" insert --,--; after "chip" insert --,--.
Column 10, line 21, after "shows" insert --a--.
Column 10, line 32, after preferably insert --are--.
Column 10, line 36, "dispose" should read --disposed--.
Column 13, line 41, "Second" should read --second--.
Column 15, line 33, delete "greeter" and insert therefor --greater--.
Column 15, line 45, after "bending" insert --the--.
Column 16, line 38, after "step" insert --,--.

MAILING ADDRESS OF SENDER:
Michael J. Doherty
LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP
600 South Avenue West
Westfield, New Jersey 07090

PATENT NO. 6,794,202

No. of additional copies

8 DEC 2004

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,794,202 *B2*
DATED : September 21, 2004
INVENTOR(S) : Masud Beroz and David Light

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, line 25, after "integrated circuits" insert --,--.
Column 1, line 52, delete "are" and insert therefor --is--.
Column 4, line 53, after "combination" insert --of--.
Column 5, line 33, delete ",".
Column 5, line 55, delete "in" and insert therefor --is--.
Column 9, line 19, after "as" insert --,--; after "chip" insert --,--.
Column 10, line 21, after "shows" insert --a--.
Column 10, line 32, after preferably insert --are--.
Column 10, line 36, "dispose" should read --disposed--.
Column 13, line 41, "Second" should read --second--.
Column 15, line 33, delete "greeter" and insert therefor --greater--.
Column 15, line 45, after "bending" insert --the--.
Column 16, line 38, after "step" insert --,--.

MAILING ADDRESS OF SENDER:

Michael J. Doherty
LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP
600 South Avenue West
Westfield, New Jersey 07090

PATENT NO. 6,794,202

No. of additional copies

8 DEC 2004